

# Specification Errata

The 1st harmonic distortion specification for the PCIP-SST is incorrect as stated in the user's guide for the board. This specification has been corrected as follows:

<b>1st Harmonic Distortion</b>	<b>New Specification</b>
1 Hz to 499 kHz	Down $\geq$ 30 dB
500 kHz to 5 MHz	Down $\geq$ 25 dB

# Specification Errata

The 1st harmonic distortion specification for the PCIP-SST is incorrect as stated in the user's guide for the board. This specification has been corrected as follows:

<b>1st Harmonic Distortion</b>	<b>New Specification</b>
1 Hz to 499 kHz	Down $\geq$ 30 dB
500 kHz to 5 MHz	Down $\geq$ 25 dB