



Release Notes

SAS/SATA InFusion Version 1.20

- This release contains the following components, which are necessary for the operation of the product:
 - InFusion™ Application Version 1.20 Build 66.
 - InFusion™ SAS/SATA Bus Engine Version 1.20 Build 12.
 - InFusion™ SAS/SATA Firmware Version 1.02 Build 34.
- This release adds the following new features to the scenarios in the InFusion™ system:
 - Data Capture capabilities. Capture of a data dword capability allows later reuse of captured data for detection and/or data substitutions.
- This release fixes the following issues that were found in release 1.11:
 - Multiple substitutions on the same frame can now be done.
 - Align frequency is now correctly maintained during SATA Hold handling as well.
 - Some connectivity issues on some systems have been improved.
- **IMPORTANT: Existing scenarios stored in InFusion box must be updated.**
 - Any existing scenarios that have been stored in the InFusion box must be updated to be compatible with the new BusEngine v1.20. (Scenarios that are on the PC will be updated as they are downloaded; this applies only to scenarios that are already downloaded to the InFusion box). It is not sufficient just to update the BusEngine, the scenarios stored on the box must also be updated. Scenarios are automatically updated when they are downloaded. After updating the BusEngine version to v1.20, download all scenarios to the box again using the instructions on page 84 of the InFusion User Manual.