



Release Notes

USBTracer/Trainer™ product – 2.30

What's New

- This is version 2.30 of the USBTracer/Trainer™ product.
- This release contains the following components, which are necessary for the operation of the product:
 - USBTracer™ Application Version 2.30.
 - USBTracer™ Bus Engine Version 2.57 (Analyzer + Host Emulation) and Version 2.59 (Analyzer + Device Emulation).
 - USBTracer™ Firmware Version 1.09.
- This release includes the following updates:
 - Three new Transaction Levels were added: PTP Transaction, PTP Object and PTP Session.
 - With the introduction of these new Transaction Levels the following decodes are now supported:
 - PictBridge
 - MTP
 - PTP
 - The following decodes were updated to match the latest specifications:
 - Monitor (HID extension)
 - Physical Interface (force-feedback extension to HID)
 - Power (HID extension)
 - HUT (HID)
 - Point of sale Devices (HID extension)
- This release includes the following fixes:
 - Fix Wire Adapter decoding problems.
 - Fix failure of Legacy Descriptor decoders in Transfer view.
 - Fix Audio Class Decoding problems.
 - Fix inability to update FW and Bus Engine in Advisor in versions 2.15 and 2.2x.
 - Fix msb<->lsb incorrect order in Transfer Level Request Field display.
 - Fix crash when hitting Intelliframe/Bitstream button in Gen file.
 - Fix hiding by host/address/endpoint for control transactions and transfers.
 - Fix crash when opening of USB Gen Files from Automation client. They now open explicitly when you start generation.