# SERVICE MANUAL

[NMP Part No. 0275568]

# NPW-2NX Series Cellular Phones

NPW-2NX Issue 1 01/02



### **Amendment Record Sheet**

Amendment No	Date	Inserted By	Comments
	01/02	J Fraser	Issue 1

### NPW-2NX Series Cellular Phones Service Manual – Overall Manual Contents

#### **Service Manual comprising**

#### **NPW-2NX Series Transceiver booklet comprising**

Chapter 1: Foreword

Chapter 2: General Information

Chapter 3: System Module LN-8

Chapter 4: Parts List

Chapter 5: Variants

Chapter 6: Service Software Instructions

Chapter 7: Service Tools

Chapter 8: Disassembly / Assembly

Chapter 9: Troubleshooting

Chapter 10: Accessories

Chapter 11: Car Kit

Chapter 12: Schematics

#### **IMPORTANT**

This document is intended for use by qualified service personnel only.

### **Company Policy**

Our policy is of continuous development; details of all technical modifications will be included with service bulletins.

While every endeavour has been made to ensure the accuracy of this document, some errors may exist. If any errors are found by the reader, NOKIA MOBILE PHONES Ltd should be notified in writing.

#### Please state:

Title of the Document + Issue Number/Date of publication Latest Amendment Number (if applicable) Page(s) and/or Figure(s) in error

Please send to: Nokia Mobile Phones Ltd

PAMS Technical Documentation

PO Box 86

FIN-24101 SALO

Finland

### Warnings and Cautions

Please refer to the phone's user guide for instructions relating to operation, care and maintenance including important safety information. Note also the following:

#### Warnings:

- CARE MUST BE TAKEN ON INSTALLATION IN VEHICLES FITTED WITH ELECTRONIC ENGINE MANAGEMENT SYSTEMS AND ANTI-SKID BRAKING SYSTEMS. UNDER CERTAIN FAULT CONDITIONS, EMITTED RF ENERGY CAN AFFECT THEIR OPERATION. IF NECESSARY, CONSULT THE VEHICLE DEALER/ MANUFACTURER TO DETERMINE THE IMMUNITY OF VEHICLE ELECTRONIC SYSTEMS TO BE ENERGY.
- 2. THE HANDPORTABLE TELEPHONE MUST NOT BE OPERATED IN AREAS LIKELY TO CONTAIN POTENTIALLY EXPLOSIVE ATMOSPHERES EG PETROL STATIONS (SERVICE STATIONS), BLASTING AREAS ETC.
- 3. OPERATION OF ANY RADIO TRANSMITTING EQUIPMENT, INCLUDING CELLULAR TELEPHONES, MAY INTERFERE WITH THE FUNCTIONALITY OF INADEQUATELY PROTECTED MEDICAL DEVICES. CONSULT A PHYSICIAN OR THE MANUFACTURER OF THE MEDICAL DEVICE IF YOU HAVE ANY QUESTIONS. OTHER ELECTRONIC EQUIPMENT MAY ALSO BE SUBJECT TO INTERFERENCE.

#### **Cautions:**

- 1. Servicing and alignment must be undertaken by qualified personnel only.
- 2. Ensure all work is carried out at an anti-static workstation and that an anti-static wrist strap is worn.
- 3. Ensure solder, wire, or foreign matter does not enter the telephone as damage may result.
- 4. Use only approved components as specified in the parts list.
- 5. Ensure all components, modules screws and insulators are correctly re-fitted after servicing and alignment. Ensure all cables and wires are repositioned correctly.