



7400 & 7600 Precision LCR Meters



Description	QT P/N	Description	QT P/N
Rack Mount Kit	7000-00	4-BNC to Chip Component Tweezers	7000-05
4-BNC to 4-BNC (1m) Cable Lead Set	7000-01	Axial/Radial Test Fixture w/4-BNC cable	7000-06
4-BNC to 4-BNC (2m) Cable Lead Set	7000-02	Chip Component Test Fixture w/4-BNC cable	7000-07
4-BNC to 2-Kelvin Clip Lead Set	7000-03	High Voltage Test Fixture w/4-BNC cable	7000-08
4-BNC to 4-Alligator Clip Lead Set	7000-04	Calibration Kit w/4-BNC cable	7000-09

1910 Inductance Analyzer & 1920 Precision LCR Meter



1910 Inductance Analyzer		1920 Precision LCR Meter	
Description	QT P/N	Description	QT P/N
Axial/Radial Component Test Fixture	1700-01	Axial/Radial Component Test Fixture	1700-01
Axial/Radial Remote Test Fixture	1700-02	Axial/Radial Remote Test Fixture	1700-02
4-BNC to 2-Kelvin Clip Lead Set	1700-03	4-BNC to 2-Kelvin Clip Lead Set	1700-03
4-BNC to 4-Banana Plug Lead Set	1700-04	4-BNC to 4-Banana Plug Lead Set	1700-04
4-BNC to Chip Component Tweezer	1700-05	4-BNC to Chip Component Tweezer	1700-05
4-BNC to 4-BNC (1m) Cable Lead Set	7000-01	4-BNC to 4-BNC (1m) Cable Lead Set	7000-01
4-BNC to 4-BNC (2m) Cable Lead Set	7000-02	4-BNC to 4-BNC (2m) Cable Lead Set	7000-02
Low Volt. Chip Component Test Fixture	7000-07	Low Volt. Chip Component Test Fixture	7000-07
Rack Mount Flanges	2000-16	Rack Mount Flanges	2000-16


*** = Accessory is STANDARD with QuadTech Instrument**

More LCR Products & Accessories

1750, 1730 & 1710 LCR Digibridges




Description	QT P/N	Description	QT P/N
Axial/Radial Component Test Fixture	1700-01	4-BNC to 4-Banana Plug Lead Set	1700-04
Axial/Radial Remote Test Fixture	1700-02	4-BNC to Chip Component Tweezer Set	1700-05
4-BNC to 2-Kelvin Clip Lead Set	1700-03*		



1693 & 1689M Digibridges (4-BNC Terminal Leads)




Description	QT P/N	Description	QT P/N
Remote Test Fixture	1689-9600	Rack Mount Kit	1689-9611
4-BNC to 4-BNC Extender Cable	1689-9602*	4-BNC to 2-Kelvin Clip Extender Cable	7000-03
Calibration Kit	1689-9604	4-BNC to Chip Component Tweezers	7000-05
GO/NO GO Test Fixture (Requires 1658-9620)	1689-9605		



*** = Accessory is STANDARD with QuadTech Instrument**

More LCR Products & Accessories

1692 & 1689 Digibridges (Axial/Radial Fixture)





Description	QT P/N	Description	QT P/N
A/R Plug-in to 4-Banana (Alligator) Cable Set	1657-9600	Calibration Kit	1689-9604
A/R Plug-in to 4-874 Connectors Cable Set	1688-9600	GO/NO GO Test Fixture (Requires 1658-9620)	1689-9605
Digibridge BNC Adaptor	1689-9601	4-BNC to 2-Kelvin Clip Extender Cable	7000-03
4-BNC to 4-BNC Extender Cable	1689-9602	4-BNC to Chip Component Tweezers	7000-05

1320 & 1320S Bias Current Source & Slave



1320S BCS Slave Unit		1320 Bias Current Source	
Description	QT P/N	Description	QT P/N
40A BNC/Spade to Alligator Lead Set	1320S-01*	2-BNC/2-Banana to Kelvin Lead Set	1320-01*
20cm (8") Spade to Spade Lead Set	1320S-02*	4-BNC Lead Box to Lead Box Set	1320-02
100cm (40") Spade to Spade Lead Set	1320S-03*	4-BNC to 4-BNC (12") Cable Lead Set	1320-03
25-Pin Slave Interconnect Cable	1320S-04*	9-Pin LCR Link Interconnect Cable	1320-04
		24-Pin Handler Interconnect Cable	1320-05
		36-Pin QT 7000 Interconnect Cable	1320-06
		37-Pin QT 1910 Interconnect Cable	1320-07



* = Accessory is STANDARD with QuadTech Instrument

The information presented here is subject to change and is intended for general information only

©QuadTech, Incorporated

Telephone: 1- 800-253-1230, Website: <http://www.quadtech.com>

Printed in U.S.A.

PN 035084/A2

September 2002