	別
(片(O)	Ш

Reason for

Modification:

Model: Model U-C1 Duplex Unit (AD430)

From: 1st Tech. Support Sec. Service Support Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modified Article: Control Board

#### Modification Bulletin

	Date: 22-Mar-05 Prepared			No.: MB509001	
Prepared			by: S.	Tomoe	
t.					
☐ Vend	lor ch	ange	☐ To m	neet standards	
☐ Vendor change ☐ To improve reliability			(	)	

**PAGE: 1/1** 

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G3035115	G3035120	Duplex Control Board	1-1	X/O	5	14	

**Change:** The materials for this part were changed to more environmentally-friendly types. **Reason:** This is part of Ricoh's ongoing application of in-house environmental standards.

	別
(片(O)	Ш

### **M**odification **B**ulletin

**PAGE: 1/1** 

Model: Model U-C1	Duplex Unit (AD430)	e: 22-Mar-0	5	No.: MB509002	
Modified Article: P	hotosensor		Prepared	by: S.	Tomoe
From: 1st Tech. Sup	port Sec. Service Support Dep				
Reason for	☐ Parts catalog correction	☐ Vendor ch	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improv	e reliability	(	)
	☐ Part standardization	Other			

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AW010048	AW010106	Photosensor	1-1	0/0	5	24	

**Change:** The material for this part was changed to more environmentally-friendly type. **Reason:** This is part of Ricoh's ongoing application of in-house environmental standards.

## RIGOH

#### Modification Bulletin

**PAGE: 1/1** 

Model: Model U-C1 Duplex Unit (AD430) Date					5	No.: MB509003
Modified Article: Motors, Harnesses, and Clutch					by: S.	Tomoe
From: 1st Tech. Sup	port Sec. Service Support Dep	ot.				
				ange	☐ To m	neet standards
Modification: ☐ To facilitate assembly ☐ To in			prove	e reliability	(	)
	☐ Part standardization	⊠ Other	-			

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AG070014	AG070514	Magnet Catch	1-1	X/O	3	14	
G3037290	G3037292	Reverse Motor	1-1	X/O	5	12	
G3037315	G3037317	Transport Motor – DC2.2W	1-1	X/O	7	10	
AW020056	AW020160	Photointerruptor	2-2	X/O	7	17	
		·			5	11	
G3037420	G3037421	Link Solenoid	1-1	X/O	5	13	
G3035335	G3035337	Duplex Sensor Harness	1-1	X/O	5	15	
B5095470	B5095331	Duplex Unit Harness	1-1	X/O	5	16	
AF020538	AF020638	Duplex Reverse Roller	1-1	X/O	5	20	
AF020540	AF020639	Transport Roller - 2nd	1-1	X/O	7	4	

**Change:** The materials for these parts were changed to more environmentally-friendly types.

**Reason:** This is part of Ricoh's ongoing application of in-house environmental standards.

**RCL (Japan) Production** 

Model	V/Hz	Destination	Code	Serial Number
AD430		All RICOH subsidiaries, NRG, SAVIN	B509-01	J2956200001
AD430	220-240/50, 60	Infotec	B509-26	5P48350001

# RIGOH

### **M**odification **B**ulletin

	AG	<b>C.</b> 1	

Model: Model U-C1 Duplex Unit (AD430)  Date					5	No.: MB509004
Modified Article: E	Exchange pawl		Prepared	by: S.	Tomoe	
From: 1st Tech. Sup	pport Sec. Service Support Dep	ot.				
Reason for	☐ Parts catalog correction	☐ Vendor change ☐ To meet stand			neet standards	
Modification: ☐ To facilitate assembly			☐ To improve reliability		(	)
	☐ Part standardization	Othe	r			

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G3037475	G3037477	Exchange Pawl	1-1	X/O	3	12	

**Change:** The materials for these parts were changed to more environmentally-friendly types.

**Reason:** This is part of Ricoh's ongoing application of in-house environmental standards.

**RCL (Japan) Production** 

Model	V/Hz	Destination	Code	Serial Number
AD430	120/60	All RICOH subsidiaries,	B509-01	J2956200001
		NRG, SAVIN		
AD430	220-240/50, 60	Infotec	B509-26	5P48350001