$\Box$	ПГ
	ПП

Reason for

Modification:

## Modification Bulletin

Date: 28-Oct-04			No.: MB726001			
t.	Prepared	by: M.	Tsuyuki			
<ul><li>Vendor change</li><li>To improve reliability</li></ul>		□ To m	neet standards			

**PAGE: 1/1** 

Please correct your parts catalog as follows:

From: 1st Tech. Support Sec. Service Support Dept.

□ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Model: Triton-C1 Duplex Unit (AD470)

Modified Article: Wall & Gear

Old part	New part	Description		Int	Page	Index
number	number					
B7261010		Wall(4402290800)	1	X/O	3	9
	B7267510	Wall(4402908000)				
B7262069	B7267669	GEAR(4402291060)	1	X/O	5	3

Other

ിതര	١ПЛ
=	)
いいいい	)[[

Reason for

Modification:

## Modification Bulletin

Date	e: 2-Aug-05	No.: MB726002			
Prepared by: M. Tsuyuki					
ot.					
☐ Vendor change		☐ To n	neet standards		
☐ To improve reliability		(	)		

**PAGE: 1/1** 

**Change/Reason:** The Parts Catalog was corrected as follows.

□ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Old part	New part	Des	scription	Q'ty	Int	Page	Index
number	number						
B7262114		Plastic Brush (440)	2294980)	1		7	14
	B7262214	Plastic Brush (440)	7734980)	I		7	14

☐ Other

## 3.DRIVE SECTION 2

Model: Triton-C1 Duplex Unit (AD470)

From: 1st Tech. Support Sec. Service Support Dept.

Modified Article: Plastic Brush

