

| | | | |
|----------------------------------------------------|----------------------------------------------------------|-------------------------------------------------|------------------------------------------------|
| Model: Adonis-C3 Fax Unit | | Date: 13-Apr-04 | No.: MB547001 |
| Modified Article: PCB:FCU:Ass'y | | Prepared by: Y.Urushihara | |
| From: 1st Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction | <input type="checkbox"/> Vendor change | <input type="checkbox"/> To meet standards () |
| | <input type="checkbox"/> To facilitate assembly | <input type="checkbox"/> To improve reliability | |
| | <input checked="" type="checkbox"/> Part standardization | <input type="checkbox"/> Other | |

The following has been changed due to parts standardization with the Jupiter-C1.

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|---------------|------|-----|------|-------|------|
| B0785170 | B6035170 | PCB:FCU:Ass'y | 1-1 | O/O | 3 | 10 | |

| | | | |
|----------------------------------------------------|--------------------------------------------------------------|-------------------------------------------------|------------------------------------------------|
| Model: Adonis-C3 FAX Unit | | Date: 5-Sep-05 | No.: MB547002 |
| Modified Article: NCU Board | | Prepared by: K. Takagi | |
| From: 1st Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input checked="" type="checkbox"/> Parts catalog correction | <input type="checkbox"/> Vendor change | <input type="checkbox"/> To meet standards () |
| | <input type="checkbox"/> To facilitate assembly | <input type="checkbox"/> To improve reliability | |
| | <input type="checkbox"/> Part standardization | <input type="checkbox"/> Other | |

Changes to the G3 Interface Unit Type 2045 Parts Catalog:

| Old Part Number | New Part Number | Old Description | New Description | Q'ty | Int | Page | Index No. | Note |
|-----------------|-----------------|-----------------|-------------------------|------|-----|------|-----------|------|
| 54886221 | 54886221 | NCU Board | NCU Board – 120V | 1 | - | 5 | 10 | |
| | 54886291 | | NCU Board – 230V | 1 | - | 5 | 10 | |

Change: The description for P/N 54886221 was changed, and the NCU board for the 230V machine was added.

Reason: The NCU board is not common to the 120V and 230V machines. (The NCU board for the 230V machine was missing from the Parts Catalog.)