

| | | | |
|--|---|--|--|
| Model: Model U-C1 Bridge Unit Type 1232 | | Date: 4-Apr-05 | No.: MB482001 |
| Modified Article: Electrical parts | | Prepared by: S. Tomoe | |
| From: 1st Tech. Support Sec. Service Support Dept. | | | |
| Reason for Modification: | <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization | <input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> Other | <input type="checkbox"/> To meet standards () |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|----------------------------|------|-----|------|-------|------|
| B4825130 | B4825140 | PCB: BRB | 1-1 | X/O | 3 | 2 | |
| AA140808 | AA140847 | Shift: Exit Roller: Driven | 1-1 | X/O | 3 | 27 | |
| AX640085 | AX640091 | Fan: DC24V 1.6W | 1-1 | X/O | 3 | 31 | |

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.