RIGOH

Modification Bulletin

PAGE: 1/1

Model: Model-J CF Date			e: 26-May-0	3	No.: MG570001	
Modified Article: DIMM			Prepared	by: Hid	leki Taguchi	
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor ch		ange	☐ To n	neet standards
Modification:	odification:		nprove	e reliability	()
	☐ Part standardization	☐ Othe	r			

The contents of the System firmware DIMM have been changed. See RTB #RG570002 for the v1.07 firmware history.

Major changes made:

• The meter click counter specification has been changed so that copies made in SP mode are not counted up.

Note: Be sure to use v1.07 with engine main firmware v1.15e or later, as SC999 will occur with older engine main versions.

• Fixed centering problem when printing onto 12" x 18" paper.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G5705335	G5706687	DIMM 1 - System	1 – 1	X/X	11	6	

Trou (oupail) i roudottoii								
Model	V/Hz	Destination	Code	Serial Number				
Copier Feature Expander Type 3800C	120V, 60Hz	USA, Canada	G570-17	P6720400001				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-26	4H20320001				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-27	P6720300001				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Asia	G570-29	P6720300328				

	> nn
	ועווו
	II II n I
יאנטאו	ULLUC

PAGE: '	1/1
---------	-----

Model: Model-J CF Date			e: 29-May-0	3	No.: MG570002	
Modified Article: DIMM			Prepared	by: н.٦	Гаguchi	
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor ch		ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly ☐ To improve		e reliability	()	
	☐ Part standardization	☐ Othe	r			

The Euro currency symbol has been added to 112 fonts in the following DIMM.

Related bulletins: #Rgene011, #RG570003f (Printer v1.11).

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G5706687	G5706691	DIMM 1 - System	1 – 1	X/O	11	6	

Not (dapan) i roddonon								
Model	V/Hz	Destination	Code	Serial Number				
Copier Feature Expander Type 3800C	120V, 60Hz	USA, Canada	G570-17	P6721000387				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-26	4H21020026				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-27	P6721001020				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Asia	G570-29	P6721001394				

\square	ΙПЛ
(G)(O))

Reason for

Modification:

Model: Model-J CF

Modified Article: Sensor Stopper

From: 1st Tech. Support Sec. Service Support Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

Date: 29-May-0		3	No.: MG570003	
t	Prepared	by: н.т	aguchi	
		—		
		∐ lo m	neet standards	
		()	

PAGE: 1/1

The shape of the following has been changed to ensure it does not interfere with the Rear Scanner Cover. The part name was also changed.

☐ Other

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A1931793		Scanner Home Sensor Stopper	1 – 1	X/O	7	23	
	G5701225	Shielding Plate					

Model	V/Hz	Destination	Code	Serial Number
Copier Feature Expander Type 3800C	120V, 60Hz	USA, Canada	G570-17	P6720500051
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-26	4H20620001
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-27	P6720500445
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Asia	G570-29	P6720500670

വതര	ПΠ
]GO	۱ň۱
T(O)(O)	ш

PAGE:	1/1
-------	-----

Model: Model-J CF Date		e: 25-Dec-0	3	No.: MG570004	
Modified Article: L	Lens Block		Prepared by: H.Taguchi		Гaguchi
From: 1st Tech. Sup	Support Sec. Service Support Dept.				
Reason for	☐ Parts catalog correction	☐ Vendor change		☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()
	☐ Part standardization	☐ Other			

The adhesive and adhesive method for the lens holder assembly components (CCD control board) has been improved to provide greater adhesive integrity against heat and operational stress, which can sometimes cause SC142.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G5702921—		Lens Block	1 - 1	X/O	7	5	
<u> </u>	→ G5702930	Lens:Holder:Ass'y					

110= (00/0011) 1 1000000				
Model	V/Hz	Destination	Code	Serial Number
Copier Feature Expander Type 3800C	120V, 60Hz	USA, Canada	G570-17	P67311xxxxx
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-26	4H2113xxxxx
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-27	P67311xxxxx
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Asia	G570-29	P67311xxxxx

വതര	ПΠ
]GO	۱ň۱
T(O)(O)	ш

PAGE: 1/1

Model: Model-J CF Date		e: 16-Feb-0	4	No.: MG570005		
Modified Article: Xenon Lamp			Prepared by: H.Taguchi			
From: 1st Tech. Sup	Support Sec. Service Support Dept.					
Reason for	☐ Parts catalog correction	☐ Vendor change		☐ To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization	☐ Othe	☐ Other			

The density of the coating applied to the Xenon lamp electrodes has been increased to further improve the efficiency of lamp warm-up.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G5702725	B1161800	Xenon Lamp – MM8	1 – 1	X/O	9	8	

NOE (bapan) i roadol				
Model	V/Hz	Destination	Code	Serial Number
Copier Feature Expander Type 3800C	120V, 60Hz	USA, Canada	G570-17	P67307xxxxx
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-26	4H2073xxxxx
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-27	P67307xxxxx
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Asia	G570-29	P67307xxxxx

000	пп
	4
GO	Ш

PAGE: 1/1

According to the second							
Model: Model-J CF			Date: 11-May-0)4	No.: MG570006	
Modified Article: ADF Exposure Glass				Prepared by: H.Taguchi			
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	☐ Parts catalog correction		Vendor change		☐ To n	neet standards	
Modification:	☐ To facilitate assembly	☑ To improve reliabili☐ Other		e reliability	()		
	☐ Part standardization						

The following was changed, because a coat was added to the exposure glass surface to prevent contamination.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B3516522		ADF Exposure Glass	1-1	X/O	3	8	
1	► BC012002	Exposure Glass:Sheet					
		Through:344X20					