

Model		Sorter for M210 (Ricoh CS1060, Savin 10 Bin Sorter for 7150, Nashua S811, infotec Sorter 9115Z)					Volt/Hz	Date of Modification	Serial Number	
Modified Article		Grounding Terminal								
Reason for Modification		To Meet Safety Standard								
Draw No.	Old Parts No.	New Parts No.	Description	A.B.C.	Q'ty Used Old → New	Inter- change- ability	Part needed for replacement by new part		Parts Catalog	
				Rank			Part No.	Description	Index No.	Page
	11000505		Pin-Mate-N-Lock							
		11000505B	Ground Terminal		1 - 1	X/O			102	9

Rank: A : Replace with new parts immediately. B : Replace with new parts at time of repair. C : Replace with new parts at time of overhaul.

Interchangeability:

(1) When old and new parts are not mutually interchangeable, use additional parts or an assembly part as indicated in "Parts needed for replacement by new part" to install the new part.

(2) The mark to the left of the slash indicates whether the old part can be used in the new machine, and the mark to the right indicates whether the new part can be used in the old machine. x = Not interchangeable o = Interchangeable

DETAILS OF MODIFICATION

To meet CSA Safety standards, the grounding terminal has been modified. Also, the vendor has been changed.

T.Ito, Manager
Copier Technical Support

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Savin 10 Bin Sorter for 7150	115/60	USA, Canada	A467-15	3240080001
Nashua S811	115/60	S. America, etc.	A467-16	133009XXXX
Ricoh CS1060	115/60	USA, Canada	A467-17	216009XXXX
infotec Sorter 9115Z	220,240/50	Europe	A467-26	378059XXXX
Ricoh CS1060	220,240/50	Europe. etc.	A490-27	216009XXXX

Model	Sorter for M210 (Ricoh CS1060, Savin 10 Bin Sorter for 7150, Nashua S811, Infotec Sorter 9115Z)	Volt/Hz	Date of Modification	Serial Number
Modified Article	Upper Guide Plate Mylar			
Reason for Modification	Part standardization with other sorter			

Due to part standardization with other sorter, the Upper Guide Plate Mylar has been changed.

Old P/N	New P/N	Description	Q'ty Used	Interchangeability	Index No.	Page
68012032	A3272032	Upper Guide Plate Mylar	1 → 1	O/O	54	3

T. Ito, Manager
Copier Technical Support

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Savin 10 Bin Sorter for 7150	115/60	USA, Canada	A467-15	3241100001
Nashua S811	115/60	S. America, etc.	A467-16	1331120001
Ricoh CS1060	115/60	USA, Canada	A467-17	2161080001
Infotec Sorter 9115Z	220, 240/50	Europe	A467-26	Service Parts Only
Ricoh CS1060	220, 240/50	Europe, etc.	A467-27	2161120001

Model	Sorter for M210 (Ricoh CS1060, Savin 10 Bin Sorter for 7150, Nashua S811, infotec Sorter 9115Z)	Volt/Hz	Date of Modification	Serial Number
Modified Article	Transistor			
Reason for Modification	Vendor change			

Due to vendor change, the following parts have been changed. The interchangeability is O/O.

Old P/N	New P/N	Description	Q'ty Used	Index No.	Page
14000135	↘ A3275700	Transistor - 2SA1015-Y	2 → 0	7	5
		Transistor - KTA1266Y	0 → 2	7	5
14000072	↘ A3275710	Transistor - 2SC372Y	1 → 0	6	5
		Transistor - KTC3198Y	0 → 1	6	5

T. Ito, Manager
Copier Technical Support

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
Savin 10 Bin Sorter for 7150	115/60	USA, Canada	A467-15	
Nashua S811	115/60	S. America, etc.	A467-16	
Ricoh CS1060	115/60	USA, Canada	A467-17	
Infotec Sorter 9115Z	220, 240/50	Europe	A467-26	
Ricoh CS1060	220, 240/50	Europe, etc.	A467-27	