
ISSUED ON: November 30, '95

Model	CS130 for Phoenix		Date of Modification	Serial Number
Modified Article	Spring - Exit Sensor			
Reason for Modification	To ensure proper operation of the exit sensor			

To ensure proper operation of the exit sensor feeler, a spring has been added.

211 241	New P/N	Description	Q'ty Used	Inter- change- ability	Parts Catalog	
Old P/N					Index No.	Page
	A5572143	Spring - Exit Sensor	0 → 1		38	5



M. Iwasa, Manager Technical Support Department

ISSUED ON: November 30, '95

MODEL NAME	V/Hz	DESTINATION	CODE	REI PRODUCTION SERIAL NUMBER
CS 130	115/60	USA, Canada	A557-15	2A7
CS 130	115/60 220, 240/50	Whole World	A557-17	A383
CS 130	115/60 220, 240/50	Whole World	A557-22	883
CS 130	220, 240/50	Europe	A557-26	3H0

## MODIFICATION BULLETIN NO. 2

## PAGE 1 OF 1

ISSUED ON: May 31, '96

Model	CS130 for Phoenix	Volt/Hz	Date of Modification	Serial Number
Modified Article	Interface Harness No serial number cut-i			formation.
Reason for  Modification	To facilitate part procurement, the interface harness used overseas has been changed to match the one used domestically.			

011 5/1	New P/N	Description	Q'ty Used	Inter- change- ability	Parts Catalog	
Old P/N					Index No.	Page
A557 5305	A557 5300	Interface Harness	1 → 1	O/O	7	3

T. Inove

T. Inoue, General Manager 1st Field Information Dept. QAC