

Model: Cattleya2 Controller E-710		Date: 11-Apr-01	No.: MG939001
Modified Article: E-710 Parts Catalog Collection		Prepared by: Chisato Tsuji	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ()
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	
	<input type="checkbox"/> Part standardization	<input type="checkbox"/> Other	

An incorrect part number for the 8.4GB IDE Hard Drive Kit was printed in the Parts Catalog.

Please correct your catalogs as follows:

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
G9395010	G9365010	8.4GB IDE Hard Drive Kit	1-1	-	3	3	

Model: Cattleya2 Controller E-710		Date: 20-Jun-02	No.: MG939002
Modified Article: E-710 Spare Parts Added (BIOS ROM)		Prepared by: Chisato Tsuji	
From: Technical Services sec. Service Planning Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ()
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	
	<input type="checkbox"/> Part standardization	<input checked="" type="checkbox"/> Other	

The following item has been newly registered as a spare part.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	G9385136	BIOSROM:X3E:RICOH:45019962	1	-	-	-	-

Note: When replacing the motherboard, the BIOS ROM can be removed from the old board and attached to the new board. Please order this part when it is lost or defective.

Model: Cattleya2		Date: 19-Jul-02	No.: MG939003
Modified Article: E-710 New System Version Release		Prepared by: Chisato Tsuji	
From: Technical Services sec. Service Planning Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

As the E-710 System Ver1.01 will be released in July 2002, the Document Package and Service Kit will be changed as follows.

For further details on the release of Ver1.01, please refer to RTB #RG939002.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G9399500	G9399501	E-710 Service Kit V.1.01 45028595	1	X/O	2	14	
G9395082	G9395117	DOC PACK ENGLISH	1	X/X	2	13	

Areas in **bold** have been changed or added:

Service Kit

G9399500 (Old)	G9399501 (New)
<ul style="list-style-type: none"> - System CD (V.1.0) - Installation Instructions 	<ul style="list-style-type: none"> - System CD (V.1.01) - Installation Instructions - Addendum (English/German/French/Italian/Spanish)

Document Package (English)

G9395082 (Old)	G9395117 (New)
<ul style="list-style-type: none"> - Getting Started - Color Guide - Job Management Guide - Printing Guide - Release Notes 	<ul style="list-style-type: none"> - Getting Started - Color Guide - Job Management Guide - Printing Guide - Addendum - Release Notes

Production Cut-In Serial Numbers

Model	Destination	Code	Serial Number
Color Controller E-710	US	G939-01	P7129010001
	Others	G939-02	P7129060001