

Model: Model S-F2		Date: 30-Jan-03	No.: RH556001
Subject: Service Manual Correction (Model S-F2)		Prepared by: M. Mano	
From: Technical Service Sec. Service Planning Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input checked="" type="checkbox"/> Other (S/M correction)		

Please apply the following corrections to your Service Manuals.

NIC FAX Service Manual:

Page 3-24, Sec. 3.6.1 START ADDRESS

Incorrect

Firmware	Start address	Firmware file type
NICF	200000H	*. rdt / *. mdt
JPEG		

Correct:

Firmware	Start address	Firmware file type
NICF	200000H	*. rdt / *. mdt
JPEG		*.bin