മ്പ	叽
IGO	吅

## Modification Bulletin

**PAGE: 1/1** 

Model: NAD 30S/30/40 Paper Bank		Da	Date: 26-Jun-02		2	No.: MA682001	
Modified Article: Parts Catalog Correction			Prepared by: Y.Urushihara				
From: Technical Ser	vices sec. Service Planning D	ept.					
Reason for Modification:	<ul><li>☑ Parts catalog correction</li><li>☑ To facilitate assembly</li></ul>	☐ Vendor change ☐ To improve reliability		☐ To m	neet standards )		
Modification.	☐ Part standardization	☐ Other					

Please apply the following correction to your Parts Catalogs.

## Addition:

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	AX400110	Heater – 230V 9W	1		11	25	

 00	
(U)(U)	101
	l n l
œ0	uu

## Modification Bulletin

**PAGE: 1/1** 

Model: NAD 30S/30/40 Paper Bank Da			te: 15-Dec-0	3	No.: MA682002		
Modified Article: Dehumidifier Harness			Prepared by: Y.Urushihara				
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	☐ Parts catalog correction			☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve reliability		(	)		
	☐ Part standardization	☐ Other					

The following has been changed due to a vendor change.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A6825320	B5425320	Dehumidifier Harness	1-1	0/0	11	24	

