

Model: LCT for Mojito-C2		Date: 26-Feb-03	No.: MB587001
Modified Article: Feed Rollers		Prepared by: F.Noguchi	
From: Technical Services Sec. Service Planning Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input checked="" type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The Paper Feed Rollers have been changed due to parts standardization and to increase their target yield from 300K to 1000K.

Note:

- 1) At PM parts replacement, be sure to check the target yield setting and change it in SP mode if necessary, depending on whether the part to be installed is old or new.
- 2) Color of the rollers:
 New type: Light blue
 Old type: Gray
- 3) Mainframes (Mojito-C2) containing ver0.15 at arrival have been fitted with the new PM parts.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AF0300050		Pick-up Roller	1 - 1	X/X	7	26	*
	AF030080	Paper Feed Roller: Pick-up					*
AF031064		Feed Roller	1 - 1	X/X	7	32	**
	AF031081	Paper Feed Roller: Feed: Manual Feed					**
AF032050		Separation Roller	1 - 1	X/X	9	4	**
	AF032080	Paper Feed Roller: Separate					**

Note * and **: as a set O/O

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
RT44	120/60	USA, Canada, S. America	B587-17	J5430100001
RT44	220-240/50, 60	Europe, Asia, Oceania, etc	B587-26	2Q50130001
RT44	220-240/50, 60	Europe, Asia, Oceania, etc	B587-27	J5430100083

Model: LCT for Mojito-C2	Date: 12-Feb-04	No.: MB587002
--------------------------	-----------------	---------------

Modified Article: Separation Torque Limiter		Prepared by: F.Noguchi	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ()
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	
	<input checked="" type="checkbox"/> Part standardization	<input type="checkbox"/> Other	

The following has been changed due to parts standardization with the Martini.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A2472900		Separation Torque Limiter	1 - 1	O/O	9	5	
	B0656399	Torque Limiter					

Model: LCT for Mojito-C2	Date: 17-Jun-04	No.: MB587003
--------------------------	-----------------	---------------

Modified Article: Separation Torque Limiter		Prepared by: F.Noguchi	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ()
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	
	<input checked="" type="checkbox"/> Part standardization	<input type="checkbox"/> Other	

The following has been changed due to parts standardization.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0656399		Torque Limiter	1 - 1	O/O	9	5	
	A2946700	Torque Limiter - 53MNXM					