Model	Soter Adapter for F90/F85	Volt/Hz	Date of Modification	Serial Number
Modified Article	Transport Roller			
Reason for				
Modification	To improve reliability and durability of transport roller			
modification				

Under high humidity and high temperature conditions, individual rollers on the transport roller assembly sometimes slip off the shaft. To improve the reliability and durability of the transport roller, the material of the rollers has been changed from ester rubber to ether rubber. The interchangeability is X/O.

Page	Index	Old P/N	New P/N	Description
3	12	68051241	A9101241	Transport Roller

T. Ito, Manager Copier Technical Support

ISSUED ON: Jan. 15, '91

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NUMBER
P.B. Type D	115/60	USA, CANADA	A910 - 11	010XXXX
SAVIN 7400 Sorter	115/60	USA, CANADA	A910 - 15	010XXXX
RICOH Sorter Adapter Type D	115/60	USA, CANADA	A910 - 17	010XXXX
NASHUA SA — D	220/50	EUROPE, etc.	A910 - 25	010XXXX
KALLE Type D	220/50	EUROPE	A910 - 26	010XXXX