160)[[]
[(片(D))[[

Modification **B**ulletin

	PAGE: 1/1

Model: Model J-C1/P3 Booklet Finisher Da			ate: 4-Feb-	05	No.: MB602001	
Modified Article: Parts Catalog Correction				Prepared	by: H. So	meya
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	□ Parts catalog correction	☐ Vendor	cha	ange	Other	
		☐ To impr	OVE	e reliability	☐ To mee	et standards
	☐ Part standardization	☐ Product Safe		afety	()

Incorrect Part Number	Correct Part Number	Description	Q'ty	Int	Page	Index	Note
V4121P010	V4121P004	Bracket - Rail	1 - 1		7	21	

Change: P/N change only. **Reason:** The wrong P/N was listed in the Parts Catalog.

	ПП
(G(0)	삚

Modification **B**ulletin

PAGE:	1/1

Model: Model J-C1/P3 Booklet Finisher Da			ate: 12-Apr	·-05	No.: MB602002	
Modified Article: Parts Catalog Correction					by: H. So	meya
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	□ Parts catalog correction	☐ Vendor	ch	ange	Other	
Modification:	☐ To facilitate assembly	☐ To improve re		e reliability	☐ To me	et standards
	☐ Part standardization	☐ Product Safety		afety	()

Incorrect Part Number	Correct Part Number	Description	Q'ty	Int	Page	Index	Note
V4099K603	V4121K155	Front Sub Frame	1 - 1		33	23	

Change: P/N change only. **Reason:** The wrong P/N was listed in the Parts Catalog.

RIGOH

Modification Bulletin

PAGE: 1/2

Reissued: 5-Sep-05

Model: Model J-C1/P3 Booklet Finisher Da	Date: 21-Jul-05	No.: MB602003a
--	-----------------	----------------

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Part information for Model J-C2			Prepared by: H.Someya		
From: 1st Tech. Support Sec. Service Support Dept.					
Reason for	☐ Parts catalog correction	☐ Vendor ch	ange	☐ To meet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization	Other			

Change: The parts in the table were changed or added. **Reason:** The Booklet Finisher for Model J-C2 was released.

J-C2

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
V4114P403	V4121P431	Middle Mylar	1 – 1	X/O	11	32	
V4117P270	V4121P270	Mylar – Lower Guide	1 - 1	X/O	35	53	
V4114P409	V4110P408	Thin Paddle	1 – 1	X/O	35	41	*1
V4114P409	V4134P408	Thin Paddle	2-2	X/O	35	41	*2
V4114P363	V4110P363	Holder - Paddle	1 - 1	X/O	35	40	
	V4121K305	IC - PROGRAMMED ROM	0 – 1		39	33	NEW
V4114P404	V4121P432	Sheet – Holder	1 – 1	X/O	21	16	

J-C1

001							
Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
V4114P403	V4121P431	Middle Mylar	1 – 1	O/O	11	32	
V4117P270	V4121P270	Mylar – Lower Guide	1 - 1	O/O	35	53	
V4114P409	V4110P408	Thin Paddle	1 – 1	O/O	35	41	*1
V4114P409	V4134P408	Thin Paddle	2 – 2	0/0	35	41	*2
V4114P363	V4110P363	Holder - Paddle	1 - 1	0/0	35	40	
	V4121K305	IC - PROGRAMMED ROM	0 – 1		39	33	NEW
V4114P404	V4121P432	Sheet – Holder	1 – 1	O/O	21	16	




Modification Bulletin

PAGE: 2/2

Model: Model J-C1/P3 Booklet Finisher Date:

Date: 21-Jul-05 No.: MB602003a

Page 34:



Page 38:

