

SERVICE BULLETIN

Product : 15",17" LCD MONITOR	Bulletin No. :	01-C/M-E0029
Model : S/M150MP,S/M170MP	Bulletin Date :	July.10,2001
	ECN Date :	May.29,2000
SUBJECT : MICOM Program update		

Background: ML15,ML17 model may have small display size or color defect

If returned set have upper symptoms please upgrade Micom program with jig.

Cause : Program error

Solution: Update Program with Micom jig for TFT monitor


Application Date : May.29,2000

						(Interchangeability Code : * I.C)						
Location		OLD (before) Parts			NEW (changed) Parts						*	
No.	SEC Code Descript		ion	n SEC Code		Description				I.C		
											С	
											ı	
											1	
											1	
											1	
Туре		A type	B type	C type	е	D type	E	type	F	type	9	
Interchang	ge	OLD F arly	OLD - Farly	OLD E	arly	OLD E arl	yParts	Addition	Parts	dele	etion	
Type Code		(Parts) (Prod.)	(Parts) (Prod.)	(Parts) (P	rod.)	(Parts) (Prod.) (Non	e New)	(01d	D	el.)	
(* I.C)		NEW Late	NEW ∕Late	NEW /	Late	NEW ——►Lat	е					
Applicati	on	Reference	() Only	Defected	sets	(O) Who	le set	s ()			
Attachme	nt	Schematic	Diagram () Comp	onent	Lay-out ()	Exploded	View	()	
		Mechanica	l Diagram () None	()		Others (0)		
Product Mor	nth:	- all		Seria	I No.	(~ from)						
Published	by	: C.J.Oh	Checked	by : C. K	.Park	Approve	d by	: Y.K.Yoo				
Revision (V8.1	: July 30, 1997) Customer	Satisfactio	on Gro	oup (Pages	: 1	of	4		

SERVICE BULLETIN

MICOM PROGRAM UPGRADE PROCESS

Micom jig for TFT LCD.



Upgrade program




Operating program




- 1. Open back cover & jig connection
 - Open back cover (remove screws)





- Connect 9 pin D-sub connector to COM Port 1 of Note PC
- Conect Input power to Micom Jig.
- Connect out put 3 pin connector of Micom jig to 3 pin of Monitor.




2. Program Preparing

- Make directory when program file down loading to PC.
 Ex) MI 151
- Attach "Millet.inf file" to "FlashUpgrader.exe" file with one click drag.





- "PW364 Firmware Upgrade Wizard" windows will display
- Click 3 times the Next button"N" then "Next" button will be fade.



- Remove in-put DC jack from monitor PBA and connect again. Then down load process start.
- Click "Finish(F)" button as below picture.
- Assemble the set.

3. Color adjustment

At first conect monitor to PC and run "IBM4.exe" file. (IBM4.exe file is a kind of pattern making program)

- Make black pattern using mouse button.
- Touch 3 buttons at a time (Buttons : "CH" & "-" & "+") Then, auto color adjustment will be done



- Make full white pattern using mouse button.
- Touch 3 buttons at a time

(Buttons : "Exit" & "Menu" & "-")

Then, auto color adjustment will be done



- END -