

4. Service Item

4-1 HLP4663WX/XAC

You can search for the updated part code through ITSELF web site.

URL:<http://itself.sec.samsung.co.kr>

LOC.NO.	CODE NO.	SPEC	Q'TY
OP101	AA32-00012A	MODULE REMOCON;ORC-50HF2,38KHZ,940NM,MES	1
T0268	AA39-10007Y	CBF-POWER CORD;- ,EP2/YES,SPT-2 18AWGx2C,	1
TU201S	AA40-00122A	TUNER;TMQH2-003A,C-TV TM(SUB),NTSC,181CH	1
TU202S	AA40-00122A	TUNER;TMQH2-003A,C-TV TM(SUB),NTSC,181CH	1
M0125	BP39-00106C	CBF SIGNAL-DVI(D);HLP5063WX,24P/24P,2027	1
T0049	BP47-00016A	LAMP-BALLAST;EUC 120 P/H 11,120W P/H 11,	1
	BP47-00006A	LAMP-UHP;E23,95.25,89,mm,100W,arcgap 1.0	1
T0074	BP59-00048B	REMOCON;DLP,TM76A,47,G6148,EX,SAMSUNG,L6	1
T0015	BP64-00379A	CABINET BACK-BOT;50L3,HIPS,3.5,V0,Gray	1
T0112	BP64-00393A	CABINET-BACK, TOP;46L3,HIPS,HB,GRAY	1
T0053	BP67-00108A	SCREEN FRESNEL;46W,1021*580.5,2T	1
T0027	BP94-00484A	ASSY PCB S-DMD;HLP5063WX/XAA,L62A,ATLANT	1
T0269	BP94-00485A	ASSY PCB S-ACTUATOR/SUB DETECT;HLP5063WX	1
T0132	BP94-02140A	ASSY PCB MISC-DIGITAL;HLP5063W,L62B,ATLA	1
T0145	BP94-02140B	ASSY PCB MISC-ANALOG;HLP5063W,L62B,ATLAN	1
T0091	BP94-02140C	ASSY PCB MISC-SIDE AV;HLP5063W,L62B,ATLA	1
T0245	BP94-02140D	ASSY PCB MISC-KEY CONTROL;HLP5063W,L62B,	1
T0268	BP94-02140G	ASSY PCB MISC-RMC LED;HLP5063W,L62B,ATLA	1
T0120	BP94-02141A	ASSY PCB POWER;HLP5063WX/XAA,L62B,ATLANT	1
T0852	BP96-00571D	ASSY COVER P-MIDDLE;46L3,NO-USE(SEA)	1
M0003	BP96-00572F	ASSY COVER P-FRONT;46L3,HIPS HB,GR503,BK	1
T0158	BP96-00533C	ASSY COVER P-MAIN;L3,HIPS,V0,GR503	1
T0186	BP96-00574D	ASSY COVER P-GRILLE;46L3,SEA,HIPS HB,GR5	1
	BP96-00535C	ASSY COVER P-DUCT;50L3,ABS V0,GRY,RTI 95	1
T0129	BP96-00564A	ASSY ENGINE P-DLP PLL3;PHILIPS 120W,L3 A	1
CN268	BP96-00547A	ASSY BOARD P-JACK;ATLANTIS,NTSC,AV+S-VHS	1
T0652	BP96-00555A	ASSY LENS P-HD3 DLP OPTIC MODU;BLK,00000	1
T0131	BP96-00568C	ASSY COVER P-BACK BOT;50L3,HIPS,V0,GRY	1
IC129	MD09-00137A	IC MICOM;P-PCFM-012,P-PCFM-012,32,5V,12M	1

4-2 HLP5663WX/XAA

You can search for the updated part code through ITSELF web site.

URL:<http://itself.sec.samsung.co.kr>

LOC.NO.	CODE NO.	SPEC	Q'TY
OP101	AA32-00012A	MODULE REMOCON;ORC-50HF2,38KHZ,940NM,MES	1
T0268	AA39-10007Y	CBF-POWER CORD;- ,EP2/YES,SPT-2 18AWGx2C,	1
TU201S	AA40-00122A	TUNER;TMQH2-003A,C-TV TM(SUB),NTSC,181CH	1
TU202S	AA40-00122A	TUNER;TMQH2-003A,C-TV TM(SUB),NTSC,181CH	1
M0125	BP39-00106C	CBF SIGNAL-DVI(D);HLP5063WX,24P/24P,2027	1
T0049	BP47-00016A	LAMP-BALLAST;EUC 120 P/H 11,120W P/H 11,	1
	BP47-00006A	LAMP-UHP;E23,95.25,89,mm,100W,arcgap 1.0	1
T0074	BP59-00048B	REMOCON;DLP,TM76A,47,G6148,EX,SAMSUNG,L6	1
T0015	BP64-00379A	CABINET BACK-BOT;50L3,HIPS,3.5,V0,Gray	1
M0045	BP64-00397A	CABINET BACK-TOP;56L3,HIPS,HB,GRAY	1
T0053	BP67-00111A	SCREEN FRESNEL;56W,1257*713.5,2T	1
T0027	BP94-00484A	ASSY PCB S-DMD;HLP5063WX/XAA,L62A,ATLANT	1
T0269	BP94-00485A	ASSY PCB S-ACTUATOR/SUB DETECT;HLP5063WX	1
T0132	BP94-02140A	ASSY PCB MISC-DIGITAL;HLP5063W,L62B,ATLA	1
T0145	BP94-02140B	ASSY PCB MISC-ANALOG;HLP5063W,L62B,ATLAN	1
T0091	BP94-02140H	ASSY PCB MISC-SIDE A/V;HLP5663/6163,L62B	1
T0245	BP94-02140E	ASSY PCB MISC-KEY CONTROL;HLP5663/6163W,	1
T0268	BP94-02140G	ASSY PCB MISC-RMC LED;HLP5063W,L62B,ATLA	1
T0120	BP94-02141A	ASSY PCB POWER;HLP5063WX/XAA,L62B,ATLANT	1
T0852	BP96-00583A	ASSY COVER P-MIDDLE;56L3,HIPS,HB,GR503,S	1
M0003	BP96-00585B	ASSY COVER P-FRONT;56L3,SEA,HIPS HB,GR50	1
T0158	BP96-00533C	ASSY COVER P-MAIN;L3,HIPS,V0,GR503	1
T0186	BP96-00587B	ASSY COVER P-GRILLE;56L3,SEA,HIPS HB,GR5	1
	BP96-00535C	ASSY COVER P-DUCT;50L3,ABS V0,GRY,RTI 95	1
T0129	BP96-00564A	ASSY ENGINE P-DLP PLL3;PHILIPS 120W,L3 A	1
CN268	BP96-00547A	ASSY BOARD P-JACK;ATLANTIS,NTSC,AV+S-VHS	1
T0652	BP96-00555A	ASSY LENS P-HD3 DLP OPTIC MODU;BLK,00000	1
T0131	BP96-00568C	ASSY COVER P-BACK BOT;50L3,HIPS,V0,GRY	1
IC129	MD09-00137A	IC MICOM;P-PCFM-012,P-PCFM-012,32,5V,12M	1

4-3 HLP5663WX/XAC

You can search for the updated part code through ITSELF web site.

URL:<http://itself.sec.samsung.co.kr>

LOC.NO.	CODE NO.	SPEC	Q'TY
OP101	AA32-00012A	MODULE REMOCON;ORC-50HF2,38KHZ,940NM,MES	1
T0268	AA39-10007Y	CBF-POWER CORD;-EP2/YES,SPT-2 18AWGx2C,	1
TU201S	AA40-00122A	TUNER;TMQH2-003A,C-TV TM(SUB),NTSC,181CH	1
TU202S	AA40-00122A	TUNER;TMQH2-003A,C-TV TM(SUB),NTSC,181CH	1
M0125	BP39-00106C	CBF SIGNAL-DVI(D);HLP5063WX,24P/24P,2027	1
T0049	BP47-00016A	LAMP-BALLAST;EUC 120 P/H 11,120W P/H 11,	1
	BP47-00006A	LAMP-UHP;E23,95.25,89,mm,100W,arcgap 1.0	1
T0074	BP59-00048B	REMOCON;DLP,TM76A,47,G6148,EX,SAMSUNG,L6	1
T0015	BP64-00379A	CABINET BACK-BOT;50L3,HIPS,3.5,V0,Gray	1
M0045	BP64-00397A	CABINET BACK-TOP;56L3,HIPS,HB,GRAY	1
T0053	BP67-00111A	SCREEN FRESNEL;56W,1257*713.5,2T	1
T0027	BP94-00484A	ASSY PCB S-DMD;HLP5063WX/XAA,L62A,ATLANT	1
T0269	BP94-00485A	ASSY PCB S-ACTUATOR/SUB DETECT;HLP5063WX	1
T0132	BP94-02140A	ASSY PCB MISC-DIGITAL;HLP5063W,L62B,ATLA	1
T0145	BP94-02140B	ASSY PCB MISC-ANALOG;HLP5063W,L62B,ATLAN	1
T0091	BP94-02140H	ASSY PCB MISC-SIDE A/V;HLP5663/6163,L62B	1
T0245	BP94-02140E	ASSY PCB MISC-KEY CONTROL;HLP5663/6163W,	1
T0268	BP94-02140G	ASSY PCB MISC-RMC LED;HLP5063W,L62B,ATLA	1
T0120	BP94-02141A	ASSY PCB POWER;HLP5063WX/XAA,L62B,ATLANT	1
T0852	BP96-00583A	ASSY COVER P-MIDDLE;56L3,HIPS,HB,GR503,S	1
M0003	BP96-00585B	ASSY COVER P-FRONT;56L3,SEA,HIPS HB,GR50	1
T0158	BP96-00533C	ASSY COVER P-MAIN;L3,HIPS,V0,GR503	1
T0186	BP96-00587B	ASSY COVER P-GRILLE;56L3,SEA,HIPS HB,GR5	1
	BP96-00535C	ASSY COVER P-DUCT;50L3,ABS V0,GRY,RTI 95	1
T0129	BP96-00564A	ASSY ENGINE P-DLP PLL3;PHILIPS 120W,L3 A	1
CN268	BP96-00547A	ASSY BOARD P-JACK;ATLANTIS,NTSC,AV+S-VHS	1
T0652	BP96-00555A	ASSY LENS P-HD3 DLP OPTIC MODU;BLK,00000	1
T0131	BP96-00568C	ASSY COVER P-BACK BOT;50L3,HIPS,V0,GRY	1
IC129	MD09-00137A	IC MICOM;P-PCFM-012,P-PCFM-012,32,5V,12M	1

4-4 HLP6163WX/XAA

You can search for the updated part code through ITSELF web site.

URL:<http://itself.sec.samsung.co.kr>

LOC.NO.	CODE NO.	SPEC	Q'TY
OP101	AA32-00012A	MODULE REMOCON;ORC-50HF2,38KHZ,940NM,MES	1
T0268	AA39-10007Y	CBF-POWER CORD;- ,EP2/YES,SPT-2 18AWGx2C,	1
TU201S	AA40-00122A	TUNER;TMQH2-003A,C-TV TM(SUB),NTSC,181CH	1
TU202S	AA40-00122A	TUNER;TMQH2-003A,C-TV TM(SUB),NTSC,181CH	1
M0125	BP39-00106C	CBF SIGNAL-DVI(D);HLP5063WX,24P/24P,2027	1
T0049	BP47-00016A	LAMP-BALLAST;EUC 120 P/H 11,120W P/H 11,	1
	BP47-00006A	LAMP-UHP;E23,95.25,89,mm,100W,arcgap 1.0	1
T0074	BP59-00048B	REMOCON;DLP,TM76A,47,G6148,EX,SAMSUNG,L6	1
T0015	BP64-00379A	CABINET BACK-BOT;50L3,HIPS,3.5,V0,Gray	1
M0045	BP64-00397A	CABINET BACK-TOP;56L3,HIPS,HB,GRAY	1
T0053	BP67-00112A	SCREEN FRESNEL;61W,1381*790,1.5T	1
T0027	BP94-00484A	ASSY PCB S-DMD;HLP5063WX/XAA,L62B,ATLANT	1
T0269	BP94-00485A	ASSY PCB S-ACTUATOR/SUB DETECT;HLP5063WX	1
T0132	BP94-02166A	ASSY PCB MISC-DIGITAL;HL-P6163W,L62B	1
T0145	BP94-02140B	ASSY PCB MISC-ANALOG;HLP5063W,L62B,ATLAN	1
T0091	BP94-02140H	ASSY PCB MISC-SIDE A/V;HLP5663/6163,L62B	1
T0245	BP94-02140E	ASSY PCB MISC-KEY CONTROL;HLP5663/6163W,	1
T0268	BP94-02140G	ASSY PCB MISC-RMC LED;HLP5063W,L62B,ATLA	1
T0120	BP94-02141A	ASSY PCB POWER;HLP5063WX/XAA,L62B,ATLANT	1
T0852	BP96-00584B	ASSY COVER P-MIDDLE;61L3,HIPS,HB,GR503,S	1
M0003	BP96-00586B	ASSY COVER P-FRONT;61L3,HIPS,HB,GR503,BK	1
T0158	BP96-00533C	ASSY COVER P-MAIN;L3,HIPS,V0,GR503	1
T0186	BP96-00588B	ASSY COVER P-GRILLE;61L3,SEA,HIPS HB,GR5	1
	BP96-00535C	ASSY COVER P-DUCT;50L3,ABS V0,GRY,RTI 95	1
T0129	BP96-00564A	ASSY ENGINE P-DLP PLL3;PHILIPS 120W,L3 A	1
CN268	BP96-00547A	ASSY BOARD P-JACK;ATLANTIS,NTSC,AV+S-VHS	1
T0652	BP96-00555A	ASSY LENS P-HD3 DLP OPTIC MODU;BLK,00000	1
T0131	BP96-00568C	ASSY COVER P-BACK BOT;50L3,HIPS,V0,GRY	1
IC129	MD09-00137A	IC MICOM;P-PCFM-012,P-PCFM-012,32,5V,12M	1