## CTV960905



Issue: 10/09/96 Classification: Routine

## TELEVISION TECHNICAL BULLETIN

Page 1 of 1

MODELS DV5935H

**REASON** C516 and L500, in the frame stage have been changed as follows.

**ACTION** C516 has been eliminated.

L500 has been changed from a 10uH coil to a 180R resistor ( Part number given

below).

<u>REF NO DESCRIPTION PART NUMBER PRICE CODE</u>

L500 Resistor 180R, 0.5W RR-XZ0227BMZZ AB

