

# SONY

## car stereo Service Bulletin No.78

Technical Department  
Sony Service Company  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-70

Date: June 26, 1987

Subject: Incorrect Reference Number -  
Ref. No. 60, Page 26

**Symptom:**  
(\*\*)

Note the correct reference number for the antenna connection cord shown on page 26 of the service manual.

Reference Number		Description	Part Number
Incorrect	Correct		
60	<u>75</u>	Antenna Connection Cord	1-555-488-00

