

**SONY**

Car Stereo  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** CDX-A10

**No.** 95

**Subject:** Part Number Missing - Mounting  
Brackets for XT-10


**Date:** March 11, 1988

**Symptom:**  
(\*\*)

The part number for the brackets used to mount the XT-10 tuner pack to the bottom of the CDX-A10 are not given in the service manual. The part number and bracket are shown below.

**Solution:**

Description	Part Number
Mounting Bracket, XT-10	3-331-804-01



**Reference:**

PRINTED IN U.S.A.  
CSA-14288-2

Compact Disc

CSA-14