

SONY

**Car Stereo
Service Bulletin**

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-7100

No. 112


Subject: Part Number - Power Cord Assembly **Date:** November 18, 1988

Symptom:
(**)

The Power Cord (Filter) is shown on page 40 of the service manual as separate pieces. It is now available as an assembled part. The part number is listed below:

Solution:

Description	Part Number
Power Cord Assembly	A-3217-307-A



Reference: FAX A881048

PRINTED IN U.S.A.
CSA-141188-1

CSA-14 Tuner/Tape Deck