

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-A20

No. 124

Subject: Part Number For Chuck Plate

Date: May 8, 1989

Symptom:
(**)

The chassis assembly has been changed to a new type unit with the same part number.

When the chassis assembly is replaced from the old to the new type, the chuck plate must also be replaced. The new chuck plate part number is 3-343-717-01. This new plate will also work with the old chassis.

Solution: Please add this part number to your service manual:

Description	Part Number
Chuck Plate	3-343-717-01

CD Changer
CSA-14

Reference: A890292

PRINTED IN U.S.A.
CSA-14389-1