

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-7300

No. 141

Subject: Correct Part Number For IC101

Date: May 24, 1989

Symptom:
(**)

The part number for IC101 is incorrectly listed in the service manual.

Solution: Please correct your service manual with the number listed below:

Ref. No.	Description	Part Number	
		Former	New
IC101	M5246FP	8-759-604-56	8-759-604-59

CSA-14 Tuner/Tape Deck