

**SONY**

**Car Stereo  
Service Bulletin**

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** VARIOUS CD

**No.187**

**Subject:** Lubricant Grease For CD Mechanisms **Date:** December 10, 1990

**Symptom:**  
(\*\*)

When lubrication is necessary for CD mechanisms, this grease should be used to prevent future mechanical jams.

**Solution:**

Description	Part Number
Grease Sankol, FG-84M	7-662-001-36

**Note:** This grease should not be substituted when servicing CDs.

CSA-14 Compact Disc/Portable Stereo

**Reference:**

PRINTED IN U.S.A.  
CSA-141290-1