

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-6500

No.199

Subject: Part Number Correction: IC2

Date: April 30, 1991

Symptom:
(**)

SOLUTION: Please make this correction on Page 28 of your Service Manual.

Ref. No.	Description	Part Number	
		Incorrect	Correct
IC2	NMX35920	1-805-516-11	1-808-516-11

CSA-14 Tuner /Tape Deck