

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-7280

No. 351

Subject: Description & Part Number Correction - Reference No. Q301.

Date: February 21, 1995

Symptom:

(**)

The description and part number listed on page 40 of the Service Manual for Ref # Q301, Transistor, 2SA1175-HFE, is incorrect.

Solution:

Please note the correct description and part number as shown below.

REF	DESCRIPTION		PART NUMBER	
	INCORRECT	CORRECT	INCORRECT	CORRECT
Q301	TRANSISTOR, 2SA1175-HFE	TRANSISTOR, 2SB1115A	8-729-119-76	8-729-106-60



