

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: GEN-CAR

No. 352

Subject: New Test CD Available.

Date: February 21, 1995

Symptom:

(**)

A new test CD is available through the National Parts Center. This disc is manufactured to have a close-tolerance chucking portion (1.1 mm thick, +0, -0.02mm). The disc can be used for identifying skipping problems which are actually caused by mis-chucking of discs.

Solution: Order the test CD as shown as below.

REF	DESCRIPTION	PART NUMBER
-	TEST DISC (PRECISION THICKNESS)	J-2502-012-0



