

CONFIDENTIAL

CSA-14

Sony Service Company
National Technical Services
A Division of Sony Electronics Inc.
Park Ridge, New Jersey 07656

Service Bulletin Car Stereo

Model: CDX-T60, CDX-T62, CDX-T65

No. 404R1

Subject: AVAILABILITY OF EXTENSION CABLES.

Date: December 5, 1996

Symptom:

(**)

The extension cables for debugging the listed models are now available.

Solution:

Order the extension cables that are listed in the table below.

QTY	DESCRIPTION	PART NUMBER
-2-	CABLE FROM OPTICAL TO MAIN BOARD	J-2502-024-2
-1-	CABLE FROM EHS FLEXIBLE BOARD TO MAIN BOARD	J-2502-024-1

Note: Connect one 17 pin cable to the other ,but reverse the solder connections from each other. In other words flip the cable. (see 17p connection diagram below).

