

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-4057/5500/5507/7300

No. 209

Subject: Part Clarification Knob (Handle Fitting)

Date: August 19, 1991

Symptom:
(**)

The part number for the handle fitting knob (3-340-687-01) is listed in the Accessory and Packing Material Section of Service Manuals, but there is no drawing of knob, making it difficult to identify.

Solution: A drawing of the handle fitting knob is shown below:

DESCRIPTION	PART NUMBER
KNOB (HANDLE FITTING)	3-340-687-01



HANDLE FITTING
KNOB

CSA-14 Tuner/Tape Deck