

SONY

Car Stereo Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-7130/7600

No. 230

Subject: Part Number Additions: PH-11 and PH-12



Date: March 13, 1992

Symptom:
(**)

The part numbers for photo detectors PH-11 and PH-12 on the reel board are not shown in the Service Manual.

Solution: Please add the following part information to your Service Manual:

REFERENCE NUMBER	DESCRIPTION	PART NUMBER
PH-11, PH-12	Diode, GP-2S09-B	8-719-939-11



CSA-14 Tuner/Tape Deck

Reference: FPR N0432

PRINTED IN U.S.A.
CSA-14292-2