

SONY

Car Stereo Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-U880

No. 242


Subject: Service Manual Corrections: Reference Numbers 36 and 37.

Date: August 3, 1992


Symptom:

(**) Reference numbers 36 and 37 shown in the exploded view on page 67 of the Service Manual are reversed.

Solution: Please correct you Service Manual as shown below:



INCORRECT



CORRECT

CSA-14 Tuner/Tape Deck