

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: General - Car Stereo Products

No. 245

Subject: Part Number Information: Grease and Oil

Date: August 3, 1992

Symptom:
(**)

The following lubricants have been made available for lubricating CD player mechanisms and should be used instead of all grease and oil lubricants currently being used.

Solution: Order lubricants from the chart below:

DESCRIPTION	PART NUMBER	USE
EM-30L GREASE (50G)	4-918-645-01	GREASE FOR PLASTIC GEARS
FL OIL 946P (20CC)	4-913-121-01	OIL FOR OPU SHAFT

EM-30L grease (50g)



FL oil 946P (20cc)



Compact Disc
CSA-14