

SONY

**Car Stereo
Service Bulletin**

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-7600

No.247

Subject: Part Number Addition: IC-702, Infrared Receiver

Date: August 14, 1992

Symptom:
(**) The part number for the infrared receiver IC-702 was omitted from the Service Manual.

Solution: Please add the following information in your Service Manual:

REFERENCE	DESCRIPTION	PART NUMBER
IC-702	IC, BX1393	8-749-900-36

CSA-14 Tuner/Tape Deck

