

SONY

Car Stereo
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-U880

No. 267

Subject: Part Information Corrections and Addition:

Date: November 24, 1992

Spring, Fitting
Collar
Carrying Case

Symptom:
(**)

The part numbers and descriptions for the fitting spring (Ref. 502) and the collar (Ref. 503) are incorrect in the Service Manual. Also, the part number for the detachable faceplate carrying case has been added.

Solution: Please correct your Service Manual as follows:

REF.	INCORRECT		CORRECT	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
502	CASE	3-370-129-01	SPRING, FITTING	3-367-591-01
503	SPRING, FITTING	3-367-591-01	COLLAR	3-367-590-01
----	----	----	CASE, CARRYING	3-370-129-01

CSA-14 Tuner/Tape Deck

MOUNTING HARDWARE

