

SONY.

Car Stereo
Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-5600

No. 309

Subject: Part Number Correction - Reference No. 17,
Panel, Front

Date: February 28, 1994

Symptom:

(**)

The part number listed on page 46 of the Service Manual for Ref # 17, Panel, Front, is incorrect.

Solution:

Please note the correct part number as shown below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
17	PANEL, FRONT	3-384-641-01	3-384-641-61

