

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: RM-E7

No. 26

Subject: Part Number For Battery Lid

Date: July 29, 1988

Symptom:
(**)

Solution: The part number for the battery lid is 2-394-123-01.

Miscellaneous

CSA-13

Reference:

PRINTED IN U.S.A.
CSA-13788-4