

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: DT3

No. 42

Subject: Missing Part Number

Date: November 18, 1988

Symptom:
(**)

The part number for the stereo/mono switch is not listed in the service manual.

Solution: The part number is 4-918-862-01. Please add this number to your manual.

Portable Compact Disc

CSA-13

Reference:

PRINTED IN U.S.A.
CSA-131188-2