

**SONY**

Hi-Fi Products  
**Service Bulletin**

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** D4/DT4

**No. 75**

**Subject:** New Headphone PCB Part Numbers

**Date:** May 24, 1989

**Symptom:**  
(\*\*)

There are two versions of the headphone PCB. In the old version, the headphone board is supported on the main board. In the new version, it is supported by the case.

**Solution:** Both part numbers are listed below. Please add the correct part number to your Service Manual.

| Description                             | Part Number  |  |
|---|--------------|--|
|   | Old          | New                                    |
| Headphone Jack                          | 1-565-311-11 | 1-565-311-11                           |
| Headphone PCB                           | 1-625-769-11 | 1-62 <del>5</del> -06 <del>5</del> -11 |
| L Connector/<br>Headphone Reinforcement | 1-566-090-11 | 4-926-672-01                           |

CSA-13 Portable Compact Disc

Reference:

PRINTED IN U.S.A.  
CSA-13589-6