

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D25

No. 87

Subject: Incorrect Part Number

Date: September 29, 1989

Symptom:
(**)

The part number listed in the service manual, page 28, for Q409-417 is incorrect.

Solution: Please note the correct part number below:

| Ref. No. | Incorrect | | Correct | |
|----------|-------------|--------------|-------------|--------------|
| | Description | Part Number | Description | Part Number |
| Q409-417 | 2SB798 | 8-729-101-07 | 2SB1182F5Q | 8-729-921-84 |

CSA-13 Portable Compact Disc