

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-AV910/1010

No. 96

Subject: Part Number For Top Cabinet
Is Not Listed


Date: December 29, 1989

Symptom:
(**)

The part number for the top cabinet is not listed in the service manual.

Solution: Please add the following part number to your service manual.

Description	Part Number
Top Cover	4-925-039-11



CSA-13 Receiver