

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C700

No.103


Subject: Part Number Missing - Transit Lock **Date:** February 2, 1990

Symptom:
(**)

The part number for the Transit Lock is not listed in the service manual.

Solution: Please add the part number listed below to your service manual:

Description	Part Number
Transit Lock Key	4-930-510-01



CSA-13 Compact Disc