

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive Park Ridge, New Jersey 07656

Model: SSU-800AV

No. 123

Subject: Part Number Correction - Woofer
Driver (Ref. No. 7)

Date: May 16, 1990

Symptom:
(**)

The part number listed in the service manual for the Woofer Driver, Reference Number 7, is incorrect.

Solution: Please note the correct part number shown below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
7	Woofer Driver	1-503-923-11	1-503-926-11

CSA-13 Speakers