

**SONY**

Hi-Fi Products  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** CDP-C10

**No.** 129

**Subject:** Incorrect Part Number - IC501

**Date:** August 31, 1990

**Symptom:**  
(\*\*)

Please correct the following part number in your service manual:

**Solution:**

Ref. No.	Description	Part Number	
		Incorrect	Correct
IC501	Microprocessor CXP-5016H-171Q	8-752-801-25	8-752-801-68

Compact Disc

CSA-13