

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: GENERAL - HI-FI PRODUCTS

No. 136R1

Subject: Tracking Gain Adjustment Using
Lissajous Pattern



Date: February 8, 1991

This Service Bulletin Supersedes Service Bulletin No. 136

Symptom:
(**)

To correctly set the tracking gain control, please use the following procedure:

- Solution:**
- Perform set-up and connections as in drawing.
 - Set the scope to the X-Y mode and play a YEDS-18 disc.
 - Adjust the tracking gain control for an upright ellipse on the scope.



Reference: A900866

PRINTED IN U.S.A.
CSA-13191-8

Compact Disc
CSA-13