

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-AV910/AV1010

No. 141

Subject: Service Manual Correction - Q721



Date: November 7, 1990

Symptom:
(**)

The description for Q721 is incorrectly listed in the service manual.

Solution: Please correct your service manual with the description listed below.

Ref. No.	Description		
	Former	New	Part Number
Q721	2SA1841	2SC1841	8-729-108-05



Receiver
CSA-13