

SONY.

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: VARIOUS CD

No.148

Subject: Lubricant Grease For CD Mechanisms

Date: December 10, 1990

Symptom:
(**)

When lubrication is necessary for CD mechanisms, this grease should be used to prevent future mechanical jams.

Solution:

| Description | Part Number |
|--------------------------|--------------|
| Grease Sankol, FG-84M | 7-662-001-36 |

Note: This grease should not be substituted when servicing CDs.

Compact Disc
CSA-13

Reference:

PRINTED IN U.S.A.
CSA-131290-1