

**SONY**

Hi-Fi Products  
**Service Bulletin**

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** STR-GX50ES

**No.159**

**Subject:** Incorrect Part Number - Panel Assembly


**Date:** January 7, 1991

**Symptom:**  
(\*\*)

The part number for the Panel (Base) Assembly on page 49 of the service manual is incorrect.

**Solution:** Please correct your service manual with the part number listed below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
57	Panel (Base) Assembly	X-4924-919-A	X-4924-919-1



Reference: Paul Miller

PRINTED IN U.S.A.  
CSA-131290-8